Issued: August 14, 2001 Revised: October 12, 2001

OBSERVATION REPORT #27

Verizon failed to use the proper codes when provisioning switch translations.

Issues

During System Readiness Testing, KPMG Consulting applied a standard of 95%¹ to measure Verizon's provisioning accuracy for switch translations. KPMG Consulting reviewed 71 switch translation reports and identified that reports for 11 telephone numbers did not match the switch translation codes provided by Verizon, resulting in an 84.5% switch translation accuracy. Specific discrepancies KPMG Consulting observed are outlined below:

Issue 1: Missing code for "Matrix block 900" on the 5E Type Switch

| Item | PON | VER | Telephone Number | Discrepancy |
|------|------------------|-----|---------------------|-----------------------|
| 1A | 002041TE0X000001 | AA | 7033022036 | Code "90L" not found. |
| 1B | 002041TE0X000002 | AA | 7033022037 | Code "90L" not found. |

Issue 2: Incorrect Hunting Sequence on the 5E Type Switch

| Item | PON | VER | Telephone Number | Discrepancy |
|------|------------------|-----|---------------------|---------------------------------------|
| 2A | 002071TE0X000002 | AA | 7033022045 | Hunting sequence does not match order |
| 2B | 002071TE0X000002 | AA | 7033022046 | Hunting sequence does not match order |
| 2C | 002071TE0X000002 | AA | 7033022047 | Hunting sequence does not match order |

-

¹ KPMG Consulting applied standards based on its professional judgment in the absence of (1) VA SSC-approved standards or (2) documented Verizon guidelines.

Issue 3: Missing All Switch Translation Codes on the Switch Translation Report - Rescinded

| Item | PON | VER | Telephone Number | Discrepancy |
|------|------------------|-----|---------------------|--|
| 3 | 020051TE0X000002 | AA | 7575968067 | The expected codes that were not present are as follows: o /CFV (Call Forwarding Variable) o /LIDLXA (Caller ID) o UCR=Y (Anonymous Call Rejection) o tn=XXXXXXX (Distinctive Ringing (IdentaRing)) o mastertn=XXXYYYY (Distinctive Ringing (IdentaRing)) o mdndring=b (Distinctive Ringing (IdentaRing)) |

Issue 4: Missing Hunting and Blocking Switch Translation Codes on the Switch Translation Report - Rescinded

| Item | PON | VER | Telephone | Discrepancy |
|------|------------------|-----|------------|---------------------------|
| | | | Number | |
| 4A | 020081TE0X010002 | AA | 7575998311 | The expected hunting code |
| | | | | was not present: |
| | | | | SERHLN= (Serial Hunting) |
| 4B | 020081TE0X010002 | AA | 7575998314 | The expected hunting code |
| | | | | was not present: |
| | | | | SERHLN= (Serial Hunting) |

Issue 5: Missing Hunting Switch Translation Codes on the Switch Translation Report

| Item | PON | VER | Telephone Number | Discrepancy |
|------|------------------|-----|---------------------|--------------------------------|
| 5A | 012061TE0X010002 | BB | 7033022163 | Hunting sequence not specified |
| 5B | 012061TE0X010002 | BB | 7033022164 | Hunting sequence not specified |
| 5C | 012061TE0X010002 | BB | 7038929207 | Hunting sequence not specified |

Additional Information (as of October 12, 2001)

KPMG Consulting has determined that while Issue 1, Missing code for "Matrix Block 900" on the 5E Type Switch, will remain open, the correct code is 90L, not 97M as KPMG Consulting originally reported. This error has been corrected in the October 12, 2001 version.

Additionally, KPMG Consulting has determined that Issue 3, Missing All Switch Translation Codes on the Switch Translation Report, and Issue 4, Missing Hunting and Blocking Switch Translation Codes on the Switch Translation Report, were incorrectly included in the original observation. Both Issues are actually correct and the notation "Rescinded" appears next to the table heading to indicate their removal in the October 12, 2001 version.

Assessment

Inaccurately provisioned orders are likely to negatively impact customers' views of the ordering CLECs.